

Repair Costs

Newmar 2021 KSDP 3412 / SN: 750496				As of 21-Apr-2026	
				Sub Totals:	
		Hale's Marion IL		\$4,495.64	
		Muffler Works		\$40.00	
		Freightliner NW		\$6,769.67	
		MTE, TransWest & Napa		\$44.64	
		Bish's RV Service		\$2,322.74	
		Kaiser Brake		\$242.05	
		Florence RV		\$130.00	
		NIRVC Nashville		\$1,144.51	
		REV RV Group		\$6,775.68	
		Westland Sales		\$229.23	
		Beaver Coach Sales		\$20,231.20	
		EQ Systems		\$859.37	
		Southwest Truck and RV		\$432.66	
		Maverick Mobile Service		\$475.00	
		Central Mass RV		\$350.00	
		Repairs Out of Pocket		\$44,542.39	
		YHS Repairs [Your Humble Servant]		\$11,681.25	About 67 hours repair time. Add a multiple or two of the repair time diagnosing, researching and developing solutions.
		Repair Total		\$56,223.64	
		YHS Improvements		\$7,088.75	About 41 hours plus a multiple or two diagnosing, researching and developing solutions.
		Fuel to various shops		\$843.75	Delivery time, approx 40 hours, to various shops
		Grand Total to keep it on the road for 26 months		\$64,156.14	Does NOT include scheduled maintenance
Itm	Date	Fault or Item	Cost	Vendor	Comment

Repair Costs

148	15-May-26	Replace shot Nylok wiper nuts. Torque nuts to 65 then 75 ftlb.	\$700.00	YHS	Half a day running around to Napa & other auto parts who claimed to have nuts in stock. In the end, secure with orange Permatex removable thread lock
147	13-May-26	Engine throws check engine light on start. Code 4363 2 1 is for After treatment 1 SCR Outlet Temperature Sensor – Data Erratic, Intermittent, or Incorrect.	\$43.75	YHS	Code cleared w Bluefire
146	09-May-26	Wipers start making horrible racket in torrential rain. Discover that Beaver Coach did not mask the splines or bearings before painting. Central Mass RV & Truck Repair rebuild wipers to remove grit and paint on spline and bearings. Determine Nylok nuts are shot. Should have been replaced by Beaver.	\$350.00	Central Mass RV	Wiper Technologies states Newmar spec of 40 then 65 ftlb is inadequate for these arms. 65-70 then 75 ftlb is what WT advises.
145	03-May-26	Engine throws check engine light. Code is for air cleaner, manifold sensor or turbo. Happened on hard acceleration after CC disengage for sharp curve on steep section over Blue Ridge.	\$43.75	YHS	Code cleared w Bluefire
144	28-Apr-26	Fasten recliner to floor to end all under way migration. Zero impact on comfort or usability.	\$131.25	YHS	Recliner remains in place and damage to valence prevented. Should have done this two years ago...
143	28-Apr-26	Sliding shelf in refrig does not remain in place. Add screws to fix shelf in place.	\$131.25	YHS	Drive to hardware store for screws and fine drill bits. Drill shelf and install screws
142	17-Apr-26	Remove swivel from recliner to prevent further damage to the escape window valence.	\$87.50	YHS	Recliner moves all over the place under way. Blocking with towels and pillows unsuccessful. Window side valences damaged. Swivel removal partially helped, but the recliner could still move toward the center, blocking the 'aisle'.
141	16-Apr-26	About 20 minutes from Corpus Christi, engine throws air system, particulate filter and SHUT DOWN codes.		YHS	As there is no shoulder, we drive on. About 20 minutes later all codes gone and no apparent ill effects.
140	13-Apr-26	Engine throws check engine light. Code is for air cleaner, manifold sensor or turbo. Later this code disappears and new code for particulate filter.	\$475.00	Maverick Truck & RV	Engine regen. Codes cleared..
139	06-Apr-26	Engine throws check engine light. Code is for air cleaner, manifold sensor or turbo.	\$432.66	Southwest Truck & RV	Read engine codes. Install new air filter that only had 11,000 miles of 30,000 expected life

Repair Costs

138	16-Mar-26	Add USB access to Cabin TV	\$481.25	YHS	Rear TV has a typical hanging bracket to support it. Only problem is the math challenged Newmarians mounted TV bracket too low and hanger too high so that instead of hooking with the hanger, just hangs on the hanger cutout edge. And being doubly intelligent, the TV bracket is affixed to the TV w double sided tape over about 8 sq.in. making adjustment impossible. And par for the course, one of the two lower bracket screws to the wood facia is stripped... Cutting the DS tape with a steak knife, moving the TV bracket up 1/8 inch allowed sufficient clearance to allow the bracket to slide into the hanger hooks. TV now positioned 3/4 inch left and well secured.
137	15-Mar-26	Replace Winegard Spruce router	\$262.50	YHS	Flaky since day one and will not accept mobile tether
136	04-Feb-26	3149SC Jack Control Panel	\$859.37	EQ Systems	Replace USELESS Newmar spec 13.2vdc 3149ABST jack control panel. With KIB panel reading 12.9 volts, jacks will not operate w/o parallel. This requires contortions to manual level.
135	04-Feb-26	Install and Test Jack Panel	\$87.50	YHS	
134	02-Feb-26	Repair cracking front cap	\$16,256.53	Beaver Coach Sales	Body work stress cracks below front w/s on fc bodyworked, stress cracks on ds and ps headlight corners on front cap. prepped, primed , repainted 3 colors. Removed 3m shield on front cap upper and lower, cleaned adhesive
133	02-Feb-26	Driver side slide operation ragged	\$278.64	Beaver Coach Sales	lube and 'retime' slides. Add rubber dampers to limit brackets
132	02-Feb-26	Repeat Low KIB panel investigation	\$325.08	Beaver Coach Sales	DID NOT FOLLOW INSTRUCTIONS NOT TO PROCEED W/O WIRING DIAGRAM FROM EITHER FREIGHTLINER OR NEWMAR
131	02-Feb-26	Awning only responds to one press in Android app	\$139.32	Beaver Coach Sales	Reset & Re-paired.
130	02-Feb-26	Forward DVD distribution cable defective. DVD using SAT cable	\$88.87	Beaver Coach Sales	DID NOT FOLLOW INSTRUCTIONS. Turned on TV and DVD connected w SAT cable and stopped.
129	02-Feb-26	Genset difficult to start below 50°F	\$2,028.20	Beaver Coach Sales	Glow plugs shot.
128	02-Feb-26	Rattle & Clunk while driving after slide extension, level and retraction	\$1,114.56	Beaver Coach Sales	DID NOT FOLLOW INSTRUCTIONS. Only put out slides w/o jacks. Could not locate clunks. Clunk immediately apparent when driving after extending one slide, leveling coach and retracting.
127	05-Nov-25	Reseal MCD blind ends to prevent weight bar sliding out and catching on valence hardware	\$131.25	YHS	
126	05-Nov-25	Repair tow air cap mount	\$43.75	YHS	rubber rotted likely due to exhaust heat

Repair Costs

125	05-Nov-25	Refrigerator epoxy repair lower shelf border to hold up drawer slide support.	\$350.00	YHS	Shelf border is nowhere near strong enough to support two bins of fruit and vegetables.
124	05-Nov-25	Refrigerator lower shelf add spacers to allow bins to slide back to lock.	\$87.50	YHS	Bin mounts have too much slop and sliding drawers back cause them to also slide back, preventing bin latch.
123	05-Nov-25	Refrigerator folding shelf add stops	\$43.75	YHS	Prevent auto retract from road imperfections.
122	29-Oct-25	Raise jack bodies	\$327.13	REV RV Group	RV Paws jack pads are taller than stock plate and could drag on high speed bump, drive entry etc.
121	25-Sep-25	Add switch for Radio cycle for no start... appears to have solved radio lock off	\$131.25	YHSimpr	Radio overheats on standby power and would not return to ON. Switch allowed radio to cool off to restart. Radio ultimately replaced
120	24-Sep-25	Radio roof antenna disappeared down US97. Was there in the morning when I squeegeed off the DS slide and gone in the afternoon	\$207.85	REV RV Group	stock antenna base looked robust, in fact less than 1mm plastic support
119	24-Sep-25	Replace radio and antenna, add connector for Android Auto	\$390.00	REV RV Group	
118	24-Sep-25	Kenwood DMX4710S	\$256.99	REV RV Group	
117	24-Sep-25	Rear A/C dripping from outlet side - guessed bad seal around evaporator allows 100% humid air into system	\$97.50	REV RV Group	A/C service. Covers properly installed
116	24-Sep-25	Left wiper arm started slapping right wiper. Worse on FAST use in downpours. Arm mounting bolts torque checked @ 63 FtLb.	\$117.00	REV RV Group	mounting on PS arm loose. Secured
115	24-Sep-25	Cooktop missing front two grommets which were pushed through onto the shelf below.	\$97.50	REV RV Group	Cooktop removed, grommets retrieved and installed
114	24-Sep-25	Ladder brackets not seated or sealed	\$195.00	REV RV Group	Removed, sealed and re-seated
113	24-Sep-25	HP air 2 drops below 100 PSI after a few minutes when stopped. Gauge fluctuates 2 segments while running, sometimes close to 75. Almost always drops to 75 after 30 minutes with engine off.	\$1,115.43	REV RV Group	Five difficult to access leaking air fittings replaced. Air now holds to 110 PSI after a week. NOTE: With air leaks fixed coach rides level.
112	24-Sep-25	Rear A/C dripping on bed from inlet in heavy downpour	\$741.00	REV RV Group	mounting bolts inadequately installed. Remove A/C units, clean flanges and roof. Reseal and reseal.
111	24-Sep-25	Right rear jack cushion fell off. Plates bent as too flimsy for coach on anything but a concrete pad	\$1,366.76	REV RV Group	Foam rings replaced. Feet replaced w RV Paws. Added Jack pads. Raised jacks one increment.
110	24-Sep-25	Dryer motor bearings shot from DAY ONE	\$390.00	REV RV Group	R&R Dryer
109	24-Sep-25	KIB panel 0.5VDC low on BOTH Chassis and House batteries OVERNIGHT on shorepower. Voltages correct w engine running.	\$390.00	REV RV Group	All ground and power connections checked – NO Change

Repair Costs

108	13-Aug-25	Breaker panel door falls open and hits me on the head when opening front upper middle bin door	\$43.75	YHS	Cheap plastic with little thermal stability warped until it no longer made contact.
107	01-Aug-25	Head lower cupboard shelf rail fell off	\$131.25	YHS	reglued and secured w 3 brads
106	25-Jul-25	Repair waste hose bin lock	\$87.50	YHS	Fell apart to inadequate lock washer that just flattened. New washer AND Loctite
105	25-Jul-25	Fix leaking cover in aft A/C to stop outlet water drip on bed.	\$262.50	YHS	Cover has one broken tab. Excess evaporator pipe hole sealant prevented evaporator cover seating, leaving a gap. IGNORED by Bish in 2024 AC Service
104	24-Jul-25	Replace driver side inner dual valve extension.	\$43.75	YHS	Inner pin 1/8" too short due bad crimp. Found a used one at a hole in the wall tire repair. MANY attempts made to locate
103	21-Jul-25	Move unused harness	\$87.50	YHS	Secure harness to frame
102	21-Jul-25	Fix ride fwd height link displaced by improper unused cable attachment	\$218.75	YHS	Wiring harness tie wrapped to ride height arm causing grommet to fall out of eye. Ride AND height SEVERELY impacted.
101	20-Jun-25	Adjust stove gas jets to allow low flame	\$43.75	YHS	Stove would not go below a medium boil
100	20-Jun-25	Rework wiper bkt GND to add drip loop Redone by NIRVC	\$87.50	YHS	Reworked wiper ground lead did not have a drip loop which would have corroded the terminal AGAIN
99	16-Jun-25	KIB panel dropped 0.5VDC on BOTH Chassis and House batteries OVERNIGHT on shorepower. Voltage correct w engine running.	\$953.16	NIRVC Nashville	Rework corroded chassis ground under hood. NO CHANGE
98	16-Jun-25	Replace BIM \$300. No change in operation.	\$191.35	NIRVC Nashville	BIM tested 100%. Tech error using high impedance voltmeter reading stray voltage
97	11-Jun-25	Adjust Galley 2nd level right drawer slide	\$43.75	YHS	Drawer would only half extend
96	04-Jun-25	Refrig right door lock	\$87.50	YHS	THREE times the right refrig door came open while driving on California roads, spilling contents and breaking bins. In each case, the lock slide was in place. The problem was right door is about 2mm above the left AND the latch pin is installed on an angle, allowing it to jump the track. Solution: Back the pin body out to the pin fully engages
95	20-May-25	Install AquaSana drinking water filter	\$2,800.00	YHS	Solution to failed refrig filter and fed up schlepping GALLONS of drinking water. Required removing shelving under sink and drilling counter top
94	18-May-25	Replace DARK BROWN dot cushions with tan to match décor	\$131.25	YHSimpr	Looked HIDEOUS every time a cabinet was opened
93	15-May-25	Rework WiFi Ranger mount for cooling & add forced circulation	\$131.25	YHS	Electronics got very hot with no ventilation in cabinet just below roof. Add vent and fan to circulate air
92	15-May-25	Repair front shade switch damaged by water leak	\$218.75	YHS	Control installed so water would drip in which it did with roof leak. R&R control and reposition to preclude water ingress. Add wire clip for shade & visor switch wires to allow easy access

Repair Costs

91	15-May-25	Adjust all MCD shades for proper retraction	\$43.75	YHS	Reset positions after loss from water ingress
90	15-May-25	Secure step wiring	\$87.50	YHS	Wire to steps just hanging loose. Secure harness to stop chafing
89	12-May-25	Door lock three turns out of adjustment	\$306.25	YHS	Door lock securing screws not clean or secure. Panel moved and I was locked inside. Removed panel, cleaned screws, reinstall w Loctite. Adjusted per intallation
88	12-May-25	Adjust hood port bumper	\$43.75	YHS	Hood rattled as left side bumper too far back
87	10-May-25	More stairwell tile nail	\$87.50	YHS	Additional stairwell tiles came loose over the winter.
86	10-May-25	Rotate Galley faucet to center valve lever	\$43.75	YHS	Installed with awkward and silly orientation making operation difficult
85	10-May-25	Water pump anti vibe mount reroute hoses	\$87.50	YHS	Hoses installed to cause maximum vibration. Rerouted the pump is just barely audible
84	10-May-25	Add water pump wire clamp for drip loop	\$43.75	YHS	As installed any water on wires would run into pump electrical connection
83	10-May-25	Recenter toilet & tighten mounting bolts	\$43.75	YHSimpr	Bolts not tight and toilet not square to wall
82	08-May-25	Reposition tank bay perforated filler to make more secure	\$43.75	YHS	Installed crooked and missing screw. Straighten and secure
81	08-May-25	Head seat lid wall bumper	\$43.75	YHS	Wall material is not robust and finish is paper thin. Bumper is quieter and prevents wall damage
80	08-May-25	Replace missing nut on propane ctl valve cover & add lock washers	\$43.75	YHS	Lock washers ensure nuts remain
79	08-May-25	Door side aft cabin slide trim pop rivets	\$262.50	YHS	Trim attached with short pop rivets which worked loose as no head formed due to location in 'track'. Drill out rivets, notch track behind to accept nut. Install SS screws w Loctite
78	08-May-25	Lower dinette table 4 inches. Cover gap with metal print.	\$656.25	YHSimpr	Table height was appropriate for anyone over six feet six.
77	16-Apr-25	Add divisor between AC outlet & return	\$218.75	YHSimpr	The AC inlet & outlet are both under the ceiling accent. Consequently a fair portion of the outlet is immediately returned to the AC with little circulation in the vehicle. By adding a divisor between them, more air is forced into the vehicle and more withdrawn resulting in overall better performance
76	15-Apr-25	Cabin engine hatch : fasten wall bottom to floor	\$87.50	YHSimpr	Panel that covers engine hatch latches to wall which was not secured to floor consequently rattled and flexed badly when removing cover
75	15-Apr-25	Dryer door hold open	\$43.75	YHSimpr	Dryer door closes making loading and unloading difficult. Add magnetic stop
74	15-Apr-25	Water Heater grille straighten to stop rattle	\$43.75	YHSimpr	Cover and grill bent at install and rattled w engine running. Straighten and reinstall
73	15-Apr-25	Tanks volume label for panel	\$0.00	YHSimpr	Gauge panel shows percentage, but not volume. Volume labels make calc easy

Repair Costs

72	15-Apr-25	Seal 0v wiper motor bracket gnd - has no drip loop. Replaced by NIRVC	\$43.75	YHSimpr	Add temporary sealant to prevent corrosion
71	15-Apr-25	Hood support straighten	\$43.75	YHSimpr	Hood support arm bent on delivery
70	15-Apr-25	Hood hinge screw tighten	\$43.75	YHSimpr	Hood hinge screws barely snug
69	09-Apr-25	Replace Viper module	\$8,091.92	Freightliner NW	
68	07-Apr-25	Steering alignment – wheel is close to centered at slow speed but 15° left @ 60MPH		Freightliner NW	steering shook after adjustment, reset to as delivered. N/C
67	11-Jan-25	Winegard Spruce Router repair	\$87.50	YHS	router flaky sent to Winegard
66	08-Jan-25	Roof leak	\$818.02	REV RV Group	Seal all suspect joints
65	08-Jan-25	Ride height uneven	\$265.50	REV RV Group	worn bushing and replaced incorrect arm type
64	25-Oct-24	Head adjustable AC outlet vent	\$175.00	YHSimpr	Head AC outlet very close to rear unit turning head into a meat locker. Replace non-adjustable out with adjustable. Head now maintains reasonable temperature
63	15-Oct-24	Rear air tank bleed line to electric bay. Replace Aft air tank bleed valve	\$131.25	YHS	Simple direct line through grommet into shore power electrical bay
62	12-Oct-24	Air ride adjustment as coach still not level riding	\$130.00	Florence RV	another attempt to get coach to ride level
61	01-Oct-24	Air ride adjustment as coach still not level riding	\$242.05	Kaiser Brake	installed leveling rod kit because rod stripped. Leveled to within ¼ inch from previous ¾ inch error when stationary
60	24-Sep-24	Radio DoA power off when hot. Added switch to disconnect power to restore operation after sufficient cool down	\$175.00	YHS	common fault with Xite unit. DC fan moves too little air to cool unit inside hot dash. Many frustrating mornings when the radio simply would not power on.
59	20-Sep-24	Cabinet above dinette sagging	\$199.00	Bish's RV Service	Partial dismantle & remount
58	20-Sep-24	Gallery back-splash coming off bulging side wall	\$199.00	Bish's RV Service	attached w clear rather than white silicone
57	20-Sep-24	P&S Fwd Slide leveling bolts lock nuts	\$199.00	Bish's RV Service	slide service
56	20-Sep-24	P&S Fwd Slide SCRAWK and bent aluminum flange	\$398.00	Bish's RV Service	center slide, grind aluminum flange, retime slide – New Fault: rattle on aft end w engine or genset running
55	20-Sep-24	Port slide aft gasket flattened for 1 ft w excess adhesive	\$49.25	Bish's RV Service	service gasket
54	20-Sep-24	SIX Bin door piston attachments: broken, stripped and missing screws	\$199.00	Bish's RV Service	added missing screws & rivets
53	20-Sep-24	Ignition switch rotates when starting	\$99.50	Bish's RV Service	fasten securely in dash
52	20-Sep-24	Loose 'columns' on slides shake considerably in motion	\$199.00	Bish's RV Service	add additional screws to secure 'columns'
51	20-Sep-24	Passenger window blind will not fully extend	\$99.50	Bish's RV Service	fix mounting and adjust blind
50	20-Sep-24	Trim above sofa poorly installed with ½in gap covered with tape	\$199.00	Bish's RV Service	secure trim, add seam tape – color only close

Repair Costs

49	20-Sep-24	Refrigerator water filter dribbles	\$482.49	Bish's RV Service	not repairable
48	08-Aug-24	Head vanity towel rack fell off into sink while traveling.	\$43.75	YHS	Add thread lock to vanity towel holder bolt which fell off into sink
47	05-Aug-24	BrakeSync HP air hose leak	\$175.00	YHS	HP hose routed too close to turbo. Replace rerouted hose and fittings.
46	05-Aug-24	Parts for Brake Sync	\$44.64	MTE, TransWest & Napa	Fittings and hose. Plenty of driving around to get parts from RV park
45	02-Jul-24	Awning LED wire mounting	\$262.50	YHS	Wire attached to awning with ½ velcro over the wire. In hot weather velcro fell off leaving wire dangling. Took much scrubbing with nasty chemicals to remove glue. 10 minutes to install proper high bond high temp clips
44	02-Jul-24	Fix engine fluid access door latch & adjust bumpers	\$262.50	YHS	Engine bay cover latch and socket did not align allowing engine bay cover to swing out [reported by travel buddy]. A lot of fussing and fiddling to get aligned. Bumper either too high or too low skewing bay cover
43	10-Jun-24	Microwave door travel catch	\$218.75	YHS	A regular drawer catch which depends on parallel surfaces was used to 'secure' the door. The door and the body are not. Solution is to mill the latch, bend the catch and attach w 2x pieces VHB tape. 5 minutes max once set up and doing a production run
42	04-Jun-24	BIM rewire Chassis Batt to A, Coach to B	\$131.25	YHSimpr	BIM installed upside down. BIM is a mechanical unit. Restore 'normal' orientation'
41	03-Jun-24	Adjust Chassis Battery Bin Door latch and grommets to align door	\$87.50	YHSimpr	Aft DS bin door installation poor. Door not square and too low
40	02-Jun-24	Add Chassis 5A Battery Tender powered from Block Heater cct	\$131.25	YHSimpr	Install Battery Tender
39	29-May-24	Battery Tender 5A	\$43.75	YHSimpr	purchase
38	24-May-24	Rear HP air tank bleed non-functional	-\$1,497.75	Freightliner NW	still not functional after 'fix'
37	24-May-24	Ride height adjustment – grommet not in arm	\$175.50	Freightliner NW	ride height still not even
36	21-May-24	Bilstein shocks	\$2,200.00	YHSimpr	Stock shocks are marshmallows. Coach rolled in turns and dove on all braking
35	21-May-24	Add four corner coach lift by Source Engineering	\$1,100.00	YHSimpr	Raises whole coach to facilitate poor entrances to parks & parking lots. Extra clearance for rail crossings, driveways
34	17-May-24	Fix Accents dropping	\$350.00	YHS	On Interstate highways when encounter a bump, accent covers fall down. This could be serious if someone up and the cover hit them. Make plastic shims to cover plugs for tighter fit in socket.
33	11-May-24	Port window washer hose partially blocked	\$87.50	YHSimpr	R&R hose. Flush washer system
32	11-May-24	Lube bin locks	\$43.75	YHSimpr	Locks likely never lubed as very stiff

Repair Costs

31	11-May-24	Vacuum basement	\$87.50	YHSimpr	Basement filthy with manufacturing debris, sawdust, metal swarf, etc.
30	10-May-24	Vacuum mount in aft closet	\$131.25	YHSimpr	Add mount for safe vacuum transport
29	10-May-24	Door screen snap replaced	\$43.75	YHSimpr	Flimsy pop rivet un-popped. Replacement screwed on
28	10-May-24	Fridge dispenser tray dbl side tape	\$43.75	YHSimpr	Water dispenser tray kept falling off during travel. Secure w low bond DS tape
27	10-May-24	Fix dash a/c vent	\$43.75	YHSimpr	vent louvers pulled out. Re-insert
26	06-May-24	Entry door insulation foam re-glue	\$43.75	YHS	Foam seal not well glued and peeling. Reglue
25	06-May-24	Screen door latch tighten	\$43.75	YHS	Latch loose in plex. Tighten
24	06-May-24	Entry door stairwell side trim	\$437.50	YHS	Due to a poor adhesive choice the wall tiles loosen and some fall off. Removal not a simple option. Attach with small brads.
23	06-May-24	Aft port floor trim re-glue	\$43.75	YHS	¼ round poorly installed and came loose. Re-glue
22	05-May-24	Exhaust tailpiece alignment	\$40.00	Muffler Works	muffler and brackets misaligned
21	05-May-24	Solar panel GND rewire	\$43.75	YHS	Bad crimp and too short wire came apart
20	05-May-24	Secure Hot Water control PCB box	\$43.75	YHS	Hot water control box just hanging on wires in aft closet box
19	05-May-24	Dinette slide accent light re-glue & wire route	\$350.00	YHS	Accent light peeling off due feed wires not secured. Re-glue accent light, secure wires to preclude further failure.
18	05-May-24	IMSE broom vacuum	\$70.00	YHSimpr	
17	21-Apr-24	Remove Glue on Dinette table	\$87.50	YHSimpr	Glue smear across half the table
16	21-Apr-24	Remove 1 x 3 inch glue smear on Step Cover border	\$43.75	YHSimpr	Goog-Off to remove spilled glue
15	20-Apr-24	Galley tilt drawer align	\$87.50	YHSimpr	Drawer faces <i>irregular</i> . Align so all are square
14	20-Apr-24	Cabinet door alignment	\$218.75	YHSimpr	To say the door faces were <i>irregular</i> is a gross understatement
13	19-Apr-24	Washer tap & cord straighten	\$131.25	YHSimpr	IDIOTIC rotary taps behind washer w ZERO room to turn. Cord routed through taps stopping rotation.
12	19-Apr-24	Clothes hangers in cabin	\$131.25	YHSimpr	Add coat hooks for jackets, etc. for easy access when slides are in
11	19-Apr-24	Awning beep	\$87.50	YHSimpr	Wind sensor beeped continuously. IDIOTIC location in weather. Sensor not weatherproof
10	18-Apr-24	Bin door latch adjust	\$131.25	YHSimpr	None of the bin latches were aligned
9	18-Apr-24	Lube hood HP air chuck fitting & protect w cover	\$43.75	YHSimpr	Fitting exposed to elements and subject to corrosion making it difficult use
8	18-Apr-24	Adjust rear closet door to stop squeak	\$43.75	YHSimpr	Sliding door squeaked on use. Adjust rollers to clear track
7	18-Apr-24	Wiper washer fluid outlets clean and position	\$87.50	YHSimpr	Window washer outlets went everywhere but the window
6	16-Apr-24	Install Battery Fill Monitors	\$87.50	YHSimpr	Install and validate battery fill levels

